



30620 Pacific Hwy S, #103,  
Federal Way, WA 98003  
(253) 941-4343



Enclosed please find the analytical report for one or more samples submitted for analysis by Polarized Light Microscopy.

**The six types of asbestos fibers are chrysotile, amosite, crocidolite, tremolite, anthophyllite and actinolite. A sample which contains more than 1% asbestos is considered positive and is defined by the EPA as an Asbestos Containing Material (ACM).**

The samples were analyzed in accordance with EPA method 600/R-93/116 and 600/M4-82-020 which has a detection limit of approximately 1%. The analyst used a stereomicroscope to visually inspect the sample to determine homogeneity and material descriptions. The sample was then viewed under a polarized light microscope to determine the presence and percentage of asbestos and non-asbestos fibers.

After analysis is complete, all paperwork is filed together, and kept in a secure locked filing cabinet. Asbestos Northwest ensures that the files will not be tampered with at any time and will only be removed if the client requests reanalysis or a modification to the report. If you have any concerns or comments, contact us at [feedback@asbestosnw.com](mailto:feedback@asbestosnw.com) or fill out our survey at [asbestosnw.com/survey](http://asbestosnw.com/survey)

Thank you,

A handwritten signature in black ink that reads "Cathy Butler".

-These results are only applicable to the **samples enclosed** with information provided by the client. This report may not be reproduced, except in full, without the approval of the laboratory. This report may not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.-



30620 Pacific Hwy S. #103, Federal Way, WA 98003  
 (253) 941-4343 NVLAP Lab Code: 200993-0

Asbestos NW Batch# *202213824*

**Bulk Samples Chain of Custody (EPA 600/R-93/116)**

Name/Company: [Redacted]  
 Address: [Redacted]  
*Olympia WA 98516*  
 Project Manager:  
 Project Location:

Date: *9/12/22*  
 Phone: [Redacted]  
 E-mail: [Redacted]  
 Project #:  
 Number of Samples: *1*

Turn around time (circle one): 1 Hour **24 Hours**

#	Sample ID	Description	Location/Comments
1		<i>ceiling tile</i>	<i>garage</i>
2			
3			
4			
5			
6			
7			
8			
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			
26			
27			
28			
29			
30			

**PAID**  CASH  
 CHECK  
 CREDIT

	Print	Sign	Company	Date	Time
Sampled by:					
Relinquished by:					
Delivered by:					
Accepted by:	<i>Sean B...</i>	<i>[Signature]</i>	Asbestos NW	<i>9/12/22</i>	<i>10:30</i>
Analyzed by:	<i>Dan La...</i>	<i>[Signature]</i>		<i>9/12/22</i>	<i>3:15</i>

\*Rush surcharge applies unless prior arrangement made with the lab



Asbestos Northwest, LLC  
 30620 Pacific Hwy S, #103, Federal Way, WA 98003  
 Ph: (253) 941-4343 Fax: (253) 941-4175



**Batch Number: 202213824**

**PLM Analysis by EPA Method 600/M4-82-020 and 600/R-93/116**

This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the U.S. Government.

**Attn:**

██████████

██████████ Olympia WA 98516

**Date Received: 9/12/2022**

**Date Analyzed: 9/12/2022**

**Samples Received: 1**

**Samples Analyzed: 1**

**Location: 6915 14th Ave NE Olympia WA 98516**

Client Sample ID	Lab Sample ID	Layer	Description	Matrix	% Non-Asbestos Fibers	% Asbestos Fibers and Type
1		1	Brown fibrous material with paint	Filler, Paint	90% Cellulose	None Detected